Inspection Report

Name of Work	:	Providing Cement Pipe 1 Mtr Dia to Ganesh Layout Park in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.
Work Order	:	EE/BTP/BBMP/E-PMT/16(9187)/WO/507/2013-14 Dated: 24.02.2014.
Agency	:	Madhiraju Chalapathi Raju
B.R. No & Date	:	517/2014-15 Dated: 31.03.2015
Bill Amount	:	10,00,000.00
Job Code	:	011-14-000014
P. Code	:	P-1771
Date of Inspection	:	16-02-2016.

The above said work providing cement pipe 1 mtr dia to Ganesh layout park in ward 11 (Kuvempunagara) Vidyaranyapura Sub Div was shown to me by Concerned AE.

The work was inspected by me along with the Concerned AE Sri Ranganath and found Satisfactory

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ವಿದ್ಯಾರಣ್ಯಪುರ ಉಪ ವಿಭಾಗ
ಯಲಹಂಕ ವಲಯ,
ಬೃ. ಬೆಂ. ಮ. ಪಾ., ಬೆಂಗಳೂರು-97.

Providing Cement Pipe 1 M dia to Ganesh Layout park in Ward No. 11 (Kuvempungara), Vidyaranyapura Sub Division



'Verified'

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ವಿದ್ಯಾರಣ್ಯಪುರ ಉಪ ವಿಭಾಗ
ಯಲಹಂಕ ವಲಯ,
ಬೃ. ಬೆಂ. ಮ. ಪಾ., ಬೆಂಗಳೂರು-97.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Providing Cement Pipe 1 Mtr Dia to Ganesh Layout Park in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ವಿದ್ಯಾರಣ್ಯಪುರ ಉಪ ವಿಭಾಗ
ಯಲಹಂಕ ವಲಯ,
ಬೃ. ಬೆಂ. ಮ. ಸಾ.. ಬೆಂಗಳೂರು-97

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT